

Under Review Notification

Raised By: Vanessa Morel

Product #: RB T103291-109

Date: 2019.10.31

Product Name: COMBINING GEARBOX TO TRANSMISSION ALIGN

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank								Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
RB T103291-109	RB T103291-109 Rev	Y	Y	N	Y	Y	N	N	N	19-1158	See below

Description of Issue:
 Issues stated on ADR (Manufacturing, dimensions issues)
 RB T103291-109 and items -1, -3, -5 and -7 must be put on **HOLD** in Plex
 RB T103291-109 Finish good stock must be put in quarantine
 Items -1, -3, -5 and -7 stock must be put in quarantine
 No new manufacturing is permitted until Engineering release new Rev
 Can remain on website with a note to contact sales for a quote. They must **NOT** be able to put the tool into cart
 'P' Part must be put on **HOLD** in Plex as well

Distribution:	VP Operations	Director of Engineering	Customer Support Manager	Technical Support
	Director of Operations	Chief Engineer	Production Engineers	Product Manager - Solutions Provider
	Director Quality Assurance	Engineering Project Managers	Production Planners	Supply Chain Director / Senior Buyer
	QC Coordinator	Engineering Clerk	Purchasing Manager	Marketing Eugene